1

United States Department of the Interior National Park Service

National Register of Historic Places Registration Form

This form is for use in nominating or requesting determinations of eligibility for individual properties or districts. See instructions in *Guidelines* for Completing National Register Forms (National Register Bulletin 16). Complete each item by marking "x" in the appropriate box or by entering the requested information. If an item does not apply to the property being documented, enter "N/A" for "not applicable." For functions, styles, materials, and areas of significance, enter only the categories and subcategories listed in the instructions. For additional space use continuation sheets (Form 10-900a). Type all entries.

V				
Name of Property				
historic name Blakeslee M	otor Company Building	125-	2670-0157	
other names/site number Same				
2. Location				
street & number 211 West Myrtl	e		not for publication	
city, town Independence			vicinity	
	KS county Montg	omery code 1	25 zip code 67301	
state Kansas code	RS County Honeg	Oldery Joseph	<u> </u>	
O Olassidia Miss				
3. Classification	Category of Property	Number of Best	ources within Property	
Ownership of Property			Noncontributing	
private	building(s)	Contributing		
public-local	district		buildings	
public-State	site		sites	
public-Federal	structure		structures	
	object	,	objects	
		1	Total	
Name of related multiple property listing	a :	Number of cont	ributing resources previously	
N/A		listed in the National Register0		
			_	
4. State/Federal Agency Certifica	tion			
Signature of certifying official Kansas State Historical S State or Federal agency and bureau	tate Historic Preserv	ation Ullicer	July 12, 1989 Date	
In my opinion, the property meet	s does not meet the Nation	al Register criteria. See	continuation sheet.	
Signature of commenting or other official			Date	
State or Federal agency and bureau			Annual Control of the	
5. National Park Service Certifica	tion			
I, hereby, certify that this property is:				
entered in the National Register.				
See continuation sheet.	•			
determined eligible for the National				
Register. See continuation sheet.				
determined not eligible for the				
National Register.				
i tutiviimi i ivgimidii		······································		
removed from the National Register				
other, (explain:)				
	Signat	ure of the Keeper	Date of Action	

Historic Functions (enter categories from instructions) Commerce/Trade: Specialty	Current Functions (enter categories from instructions) Commerce/Trade: Specialty Store		
	Commerce, frade: Specialty Store		
Store	:1		
7. Description			
Architectural Classification	Materials (enter categories from instructions)		
	foundation Concrete		
	foundation <u>Concrete</u> walls Brick		
(enter categories from instructions)	foundation <u>Concrete</u> walls <u>Brick</u>		
enter categories from instructions) Late 19th and Early 20th Century American Movements:	foundation Concrete walls Brick roof Asphalt		
(enter categories from instructions) Late 19th and Early 20th	walls Brick		

Describe present and historic physical appearance.

The Blakeslee Motor Company Building (1918) is located at 211 West Myrtle in Independence, Montgomery County, Kansas (pop. 10,598). This rectangular brick two-story flat-roofed commercial building has Classical Revival detailing. It stands on the west side of the town's central business district. The main three-bay facade faces Myrtle Street to the north. The structure is approximately 50 feet wide and 140 feet long. The Motor Company building retains substantial exterior and interior architectural integrity.

The interior is divided into three main areas with a plan based on the original function as an automobile agency. While the front showroom and rear garage are common features of this property type, the showroom mezzanine and second floor storeroom distinguish the Blakeslee building from other simpler examples. The front and rear sections are separated by transverse partition walls. There are two side stairways to the mezzanine between the mezzanine and storeroom. Both the garage and storeroom have two longitudinal rows of iron columns supporting the ceiling and roof. Originally, there was an elevator from the lower garage to the storeroom; this features was removed c. 1930.

The Motor Company building has a concrete foundation, brick walls with limestone and terra cotta ornamentation, and a flat built-up asphalt roof behind parapet walls. The main north and east facades are constructed of brown wire-cut brick laid in running bond. The west and rear walls are common red brick laid in header bond with six stretcher courses.

The main building facade is divided into three regular bays. A modern metal entrance door is centered in the middle bay. There are modern metal-covered bulkheads and three overhead lights in this bay. A multi-pane woodframe transom with three sections surmounts the entrance. One of the original iron fixtures for an entrance light remains projecting from the west pier. In the flanking bays there are smooth-cut stone bulkheads, two display windows, a woodframe lintel, and 60-light wood transoms. The pier bases are smooth-cut stone and small stone blocks

National Register of Historic Places Continuation Sheet

Section I	number	 Page	1	

ornament the piers. A gold molded terra cotta belt course crowns the transom row. There is a central terra cotta sign with "Motor-Cars" in raised letters above the entrance. A raised brick belt course and a projecting terra cotta cornice accent the eave. The cornice has a widely spaced dentil molding. There is a terra cotta cap on the parapet wall.

The ornamental treatment of the main facade extends around the northeast side of the building for two bays. A display window in the south bay has been filled with brick. There are two small windows next to these bays. A square brick flue is located in the east sidewall between the front and rear sections of the building. Two rows of six large windows in the east wall light the rear of the building. These have smooth-cut stone sills. The first floor opening to the north in this row has been filled with brick. Second floor windows are covered with white corrugate metal.

In the rear wall a central wooden garage door is flanked by two large windows. There are three windows on the second floor. All rear windows are covered with metal. The entire west wall of the building is blank. It has a stepped parapet in three sections.

The most significant feature of the building's interior is the two-story showroom. This room has an ornamental black and white tile floor with white tile base. The east third of this floor has been covered with modern asphalt tile. The lower half of the engaged piers in the showroom are covered with mottled green tile. The exterior walls are plastered. The ceiling is separated into six panels by intersecting beams. An elaborately ornamented pressed metal ceiling covers the beams and panels. Each panel had a suspended light fixture on a chain. The original fixtures have been replaced with modern fluorescent lights. There is stained wood trim around the display windows, under the mezzanine, and on the stairs. Each stairway has two flights at right angles with an intermediate landing. A small bathroom is located under the east stairway. A modern woodframe office has been constructed in the southeast corner of the showroom.

Modern fiberboard partitions enclose the two east bays of the mezzanine. A pipe railing extends along the top of the original mezzanine wall. The mezzanine and second floor showroom have narrow oak flooring. There are three rooms between the mezzanine and the storeroom in the rear.

National Register of Historic Places Continuation Sheet

Section	number		Page	2
---------	--------	--	------	---

This configuration may date from the bowling alley/dance hall of the 1930s. The mezzanine and rooms have triple stepped oak baseboard and casing. The east room has a 10-light stained oak door and bathroom fixtures. A similar door to the west has been moved to an opening in the modern partition blocking the center of the mezzanine. A 6/6 double-hung wooden window remains in the second floor opening of the east wall. The central and northwest rooms have light woodframe walls of plaster on wire screen.

Two rows of five iron columns in the storeroom support the building roof. A sprinkler system with exposed piping is suspended from the ceiling. There are paired 12/12 double-hung wooden windows in the east and south wall openings.

At the rear of the showroom a wide central opening leads to the garage. There is a wooden ramp from the showroom to the lower garage. A modern woodframe storage room has been constructed in the northeast corner of the garage. The second floor rests on steel I-beams supported on two rows of five iron columns. The garage is divided into three bays by these columns. There is a concrete floor and plastered exterior walls. Some areas of the rear wall have damaged plaster. The ceiling is fiberboard with wooden battens. A sprinkler system with exposed piping is suspended from the ceiling.

The Blakeslee Motor Company building has excellent exterior and interior architectural integrity. It appears today much as it did when completed in 1918. The building is slightly deteriorated, but is in good structural condition. Almost all alterations are minor. Where the original plan and details are obscured by modern construction, these changes could be reversed in a certified rehabilitation. The building is architecturally significant as a well preserved example of an early twentieth century auto salesroom.

8. Statement of Significance			
Certifying official has considered the	significance of this prop	erty in relation to other propertiesstatewide X locally	s:
Applicable National Register Criteria	ХА В ХС	□D	
Criteria Considerations (Exceptions)	□а □в □с	D DE F G	
Areas of Significance (enter categorie	s from instructions)	Period of Significance1918	Significant Dates 1918
Commerce		1918-1926	
		Cultural Affiliation N/A	
Significant Person N/A		Architect/Builder Unknown	

State significance of property, and justify criteria, criteria considerations, and areas and periods of significance noted above.

The Blakeslee Motor Company and Building (1918) Independence, is being nominated to the National Register under criterion A for its historical association with the local development of automobile sales and service. The property is also significant under criterion C as a distinctive example of an early twentieth century auto salesroom. When Barton Blakeslee moved into the building, a local newspaper concluded that "this building will be a model in its line for years to come." Compared with several other structures constructed for auto dealers during this period, the Blakeslee building is the best example of this type in downtown Independence because of its original design and architectural integrity.

The Independence Motor Company acquired the property where the Blakeslee building stands October 18, 1917. The South Kansas Tribune announced that "Barton Blakeslee, the Hudson auto dealer, has purchased the Henry Baden property west of the post office and will build an up-to-date auto salesroom." One week later the planned building was described and the article mentioned that the foundation would be strong enough to carry added stories as business demands. Construction did not begin until 1918. The Tribune January 2 reported that the residence west of the post office was being moved. "The old site will be converted into a modern automobile salesroom for Barton Blakeslee, who has made a fine success in the Carl-Leon annex." The annex referred to was located across Myrtle Street from the new building site.

A related news item in the <u>Tribune March 20</u>, 1918 pointed out that Jake Moore was remodeling his livery stable, the Hotel de Hoss, into an auto garage. "He has reduced his livery stock to a meagerly third of his former outfit, and it is only a short time until there will be no business for those. The demand is for speed." Barton Blakeslee profited from the demand for automobiles and the Motor Company building was evidence of his success.

The building was completed by June 12, 1918 when the <u>Tribune</u> announced that Blakeslee was moving into his new auto sales building, just west X See continuation sheet

National Register of Historic Places Continuation Sheet

Contina	number	Q	Page	3
OUCHUII	HUHHDO		i ago	

of the post office. According to the newspaper:

"Mr. Blakeslee has built up a wonderful business in the last six years, and has done so by carrying high class cars, such as the Hudson, Cadillac, and Essex cars, with the Acme and Republic trucks and the Cleveland Tractors.

This building and lot costing Mr. Blakeslee something like \$33,000 give him one of the most complete buildings in the state, and he thereby shows his confidence in the future of Independence."

The Blakeslee building represented a distinctive property type designed for auto sales and service. There was a two-story showroom with mezzanine in the front and a second floor storeroom in the rear above a lower service garage. The building's classical exterior detailing was a refined treatment appropriate for the more expensive automobiles offered by Blakeslee. As the Tribune described the building:

"It is built of brown mottled, wire-cut brick with plenty of windows, giving an abundance of light. In size 50 x 140 feet, with salesroom 50 x 50 feet with 21-foot beam ceiling, and tile floor with two wide stairways leading to the Mezzanine floor 16 x 50 for office with private offices near. Both floors and columns being beautifully decorated. In the rear of salesroom the lower floor 50 x 90 feet is for service, and the second floor same size for storage stock, all complete with electric elevator and modern conveniences, such as steam heat, electric lighted, and the Grinnell Automatic Sprinkler system, making it fire proof."

Reportedly, the International "gas buggy" was the first automobile sold in Independence beginning in 1902. The industry grew rapidly in the early years of the twentieth century. Besides the Blakeslee Motor Company, at least four other auto agency buildings from this period remain standing in downtown Independence. The Litchfield and Sawyer garage, a one-story doublefront building at 304-306 N. Penn., was constructed in 1908. The property was not used as an auto agency after 1922. The Independence Motor Car Company with W.W. and J.S. Curtin, proprietors, was built at 301 W. Main about 1912. It is a two-story building with a recessed corner entrance. The property housed an auto agency and service garage until after 1939. Comparable buildings located near the Blakeslee building were the Ernest Brothers Auto Company (1918) at 214-216 W. Main and

National Register of Historic Places Continuation Sheet

Section	number	8	Page	4
---------	--------	---	------	---

the Arnold Auto Company (c. 1925) at 215-217 W. Main. Both were one-story doublefront buildings with showrooms and rear garages. They housed automobile agencies until after 1939.

Although the Blakeslee building was "a model in its line," the business was not so successful. Blakeslee sold the property October 4, 1926 for \$35,000. He was later listed as an auto dealer at 217 N. 6th in 1929 and at 121 W. Laurel in 1931. The business did not survive the early effects of the depression. The Blakeslee family left Independence sometime between 1931 and 1935.

After Blakeslee sold the Motor Company building, another auto dealer George J. Marr, was listed as the building's tenant in 1929. Marr also lived in the building. The property belonged to Mary Shultis, Beatrice Stewart, and Muriel Noonan, heirs of A.W. Shultis. Shultis was a prominent Independence banker and capitalist.

By 1931 the property was occupied by the Plamor Bowling Alley with Wilbert Wilson and William Stotts, proprietors, Sweeby's luncheonette, managed by Morton Rees, and Albion Daggett, a confectioner. These tenants initiated a long period of the building's use as an amusement center. In 1937 and 1939 the property was also listed as the Plamor dance hall. The combined use as a bowling alley and restaurant continued for many years. The property was known as the Plamor until after 1953. In 1957 Cordie and Martha Peterson operated the bowling alley and grill under their name. The present tenant, Tri-State Electrical Supply Company, occupies only the front showroom and the lower rear garage. However, throughout the years of different tenancies the building has retained much of its integrity. Shultis Properties, the partnership which owns the building, plans a rehabilitation for another tenant who would utilize the entire building.

The Blakeslee Motor Company building has significant associations with the local development of automobile sales and service in Independence, Kansas. The building is a distinctive and well-preserved example of an early twentieth century auto sales room. The period of historical significance includes the years from 1918 until 1926 when the property housed the Blakeslee Motor Company. The period of architectural significance is associated with the date of construction, 1918. Compared with other examples of this property type, the Blakeslee building may also have regional or state-wide architectural significance.

). Major Bibliographical References	
Independence, Kansas City Directories	, 1912-1957.
Montgomery County, Kansas Register of Company Warranty Deed. 124:68. I B. Shultis Warranty Deed. 162:566	Deeds. Boden-Independence Motor Barton Blakeslee and wife Mary
South Kansas Tribune, 24 September 1917; 2 January 1918; 20 March 191	17; 17 October 1917; 21 November 18; 12 June 1918.
	See continuation sheet
Previous documentation on file (NPS): preliminary determination of individual listing (36 CFR 67)	Primary location of additional data:
has been requested	X State historic preservation office Other State agency
previously listed in the National Register	Federal agency
previously determined eligible by the National Register designated a National Historic Landmark	Local government
recorded by Historic American Buildings	University
Survey #	Other
recorded by Historic American Engineering	Specify repository:
Record #	Kansas State Historical Society
10. Geographical Data Acreage of property Less than 1 acre	
Acreage of property	
UTM References A 1 5 2 5 9 7 6 0 4 1 2 3 1 4 0 Zone Easting Northing	B Zone Easting Northing
c	
	See continuation sheet
	1 - Amont (approximately
Vances It is bounded on the east. W	rest, and south by the adjacent rette Street. The property is located
	See continuation sheet
Down Jan Lindistration	
Boundary Justification The boundary includes all property hi	Istorically associated with the
nominated building.	
	See continuation sheet
14. Form Propored By	
11. Form Prepared By name/titleDale_Nimz	
turnation	date <u>July 12, 1989</u>
street & number P.O. Box 1046	telephone 913-842-8992
city or town Lawrence	state <u>Kansas</u> zip code <u>66044</u>

